

Asset type

2. DPWP ID

Inspection for disposing assets

3.

Model and brand:

2. Serial #:

Form

181

Light Vehicle	S10	KDI	H2270001046	HIACE	ТОУОТА
5. Year			6. Hours or kilo	meters	7. Twist lock cycles
2005		133647		N/A	
	8. Genera	l descr	iption of asset o	condition	
Rust at the undercarriage and	lower body pa	rts are a	mayor issue. The	e body has minor de	ents at various spots.
Rear AC blower needs replace	ing. Ac system	is in fa	ir condition		
2 rear tires need replacing					
The engine is in fair condition	with minor oi	l leak a	t the front cranksl	naft seal.	
Mayor rust at rear undercarria	ge and front le	ft and r	ight wheel well.		
Brakes are in poor condition.	Rotor and drur	ns will	need machining it	f not replacing	
Automatic Transmission is in	fair condition	with so	metimes rough sh	ifting from 3 rd to 4 ^t	h gear
Steering links, stabilizers and	bushings will	need rep	placing which afte	erwards needs whee	el alignment.
Rear differential UV joint has	some play and	l will ne	eed replacing soon	1.	
Cab interior is in fair conditio	n with seats, d	ashboar	d consul and instr	umental dash.	
9. Recommended disposal m	ethod and ecc	nomic i	impact		
Equipment can be sold off.					
Equipment can be sold on.					
10 Comments				11 Nome data an	d signatura
10. Comments				11. Name, date an	a signature
Equipment is drivable.				C.Fernandes	:
					April 03, 2023,
12. Remarks					13. Approved by:
12. Remarks					13. Approved by.
Approved by		Revision: 4.0			Form: 181