

	<b>Inspection for disposing assets</b>		Form
			<b>181</b>

1. Asset type <b>Light Vehicle</b>	2. DPWP ID <b>S11</b>	2. Serial #: <b>RZH1016009459</b>	3. Model and brand: <b>HIACE TOYOTA</b>
5. Year <b>2006</b>		6. Hours or kilometers <b>147979</b>	7. Twist lock cycles <b>N/A</b>

<b>8. General description of asset condition</b>
The engine is in fair condition with minor oil leak at the valve cover and engine front cover
Automatic Transmission is in fair condition with minor issue on the selector switch which needs replacing.
All 4 tires are in good condition being replaced not long ago.
Power steering system has minor oil leak at steering rack
Lots of rust at undercarriage and front left and right wheel well. Rear lower wheel well and side door lower inner parts has also lots of rust.
Brakes are in fair condition.
Steering links, stabilizers and bushings are in fair condition.
Rear differential UV joint is in fair condition.
Cab interior is in fair condition with seats, dashboard consul and instrumental dash.
Ac system is in fair condition
Rust at the undercarriage and lower body parts are a mayor issue. The body has minor dents at various spots.

9. Recommended disposal method and economic impact  Equipment can be sold off.	
10. Comments  Equipment is drivable.	11. Name, date and signature  <b>C.Fernandes</b>  April 04, 2023,

12. Remarks	13. Approved by: