



**DP WORLD**

# EMPTY CONTAINER HANDLER

2003 DIESEL HYSTER H1600XM 12EC

# TECHNICAL SPECS

Capacity:  
8.5 Ton

Fuel:  
Diesel

Engine:  
Cummins QSB  
5.9C

Run hours:  
4273

Serial #:  
A214EO1957A

Model:  
H1600xm 12EC

Year:  
2003

Location: DP  
World  
Paramaribo

Condition:  
Used

2003 DIESEL HYSTER H1600XM 12EC



## Mast cylinders :

In fair condition, mast chains and horse pulley in good condition, hydraulic hoses in need of replacement due to aging..

## Differential and final drive:

Overall, in good condition. Minor oil leak at final drive right hub plug. Drive axle, shafts and joints in good condition.

# EMPTY CONTAINER HANDLER

2003 DIESEL HYSTER H1600XM 12EC

Equipment description

## Fan Blade:

Slightly damaged, minor oil leak at filter housing and front cover, engine mounting rubber in poor condition, turbo exhaust pipes corroded. Overall, in good condition

## Brakes

Brakes including the parking brake unit are all in good working condition. Tires overall in fair condition fair. Steering tires slightly worn.

## Spreader lock clamp section:

The spreader lock clamps section and clamp cylinder are in poor condition. Minor hydraulic leak at side shift cylinder

## Transmission speed

3 speed zf transmission forward and reverse in good working condition with smooth gear shifting. Transmission controls, brigade back-up radar system and back-up camera system in good condition.

## Operators Cabin:

Operators cab, interior condition is fair with some minor corroded sections. Instrument panel in good working condition. Ac, headlights, working lights, strobe light, back-up alarm in good condition.

## Hydraulics

Hydraulics, mast & spreader overall condition fair. Minor hydraulic oil leaks at main selector block valve between the various control block section. Hydraulic hoses in need of replacement due to aging. All accumulators are in good condition.

## Steering Mechanism

Fair working condition with swivel bearings and bushing already replaced. Steering cylinder have a minor hydraulic oil leak.

## Spreader overall

Condition fair, wiring harness, proximity switches and relay/fuse control unit were replaced. Solenoids and hydraulic block valve in good condition.

# EQUIPMENT PICTURES

